

TECHNICAL BULLETINDate: Aug. 22, 2017
Ref: EW0121**Teriostar2 Enhanced model:LP-2060/1040:****Firmware version 3.10 released**

To: Worldwide Business Partner's,

This Bulletin is to inform you that a new firmware version 3.10 for Teriostar LP-2060/1040 has been released.

- Changes: Version upgraded from 2.22 to 3.10.

Respectfully yours,



Hajime Murakoshi
Manager,
Global Technical Support Section
OKI Data Infotech Corporation

Back numbers of Technical Bulletins are available on Partners Plaza Web site.
Please check if you miss any of them.

1. Main improvements of firmware (version 3.10)

Additional features below:

- Store in the Printer function has been added to the authentication exemption function.
- Proxy print function has been added to the authentication print function.
- For output tray, collective setting function has been added.

Improvements features below:

- The user authentication function's operationability has been improved.
- The firmware has been modified so that error codes displayed on the jam error window's upper left are larger.
- The firmware has been modified so that the optional ActiveDirectory Authentication is not displayed. (ActiveDirectory Authentication becomes the function only for Japan)
- The scanner firmware has been upgraded for the factory operation.

For details, see the file, "LP2060LP1040_FirmwareReleaseNotes(V3.10)EN" and "LP-2060_LP-1040_Additional_Function_Guide_for_Firmware_Version_3.10_EN".

2. Download

You can download the firmware of LP-2060/1040 from a following partners plaza.

Please install the firmware from web tool or operation panel.

Please refer to "Teriostar2 Series Enhanced Model Maintenance Guidance" or the maintenance manual for the installation procedure of the firmware.

<https://www.partners-wideformat.com/>

The file name is ***T2E_FW_V3.10 zip***.

(End of Document/MS)